Occupational Safety and Health Administration

OCT

2	1	2	2	_	2	6	7	7

Required under USDL Safety and Health Regulations for Ship Repairing Language Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SECT	ION I	JAN 1 5 1982
MANUFACTURER'S NAME FRANKLIN OIL CORP. (OHIO)	EMERGENCY - 216/232-	relephone no. 3000
ADDRESS (Number, Street, City, State, and ZIP Code) 40 SOUTH PARK STREET, BEDFORD, OHIO 44146 CHEMICAL NAME AND SYNONYMS	TRADE NAME AND SYNO RUST FOIL 652-1	NYMS
CHEMICAL FAMILY	FORMULA	
	TO LES INCOMPONITO	

SECTION	J II -	HAZAF	RDOUS INGREDIENTS		~111
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL	-	
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS ,			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS				- ×	TLV
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES					(Units)
		· ·		_	

SECTION III - I	PHYSICAL DATA	
N.D.	SPECIFIC GRAVITY (H2O=1)	0.90
<u>∠ 1</u>	PERCENT, VOLATILE BY VOLUME (%)	NIL.
> 1	EVAPORATION RATE (-ether =1)	人 1
NEG.		
	N.D. ∠ 1 > 1	PERCENT, VOLATILE BY VOLUME (%) > 1 EVAPORATION RATE (-ether =1)

S	FCTION IV - FIRE AI	ND EXPLOSION HAZARD DAT	Α	
		FLAMMABLE LIMITS	Lel	Uel
FLASH POINT (Method used)	400°F. COC			
EXTINGUISHING MEDIA	FOAM, CO2, DRY CH	EMICAL.		
SPECIAL FIRE FIGHTING PR	TREAT AS A CLASS	B FIRE.		
UNUSUAL FIRE AND EXPLO	SION HAZARDS			

PAGE (1)

(Continued on reverse side)

Form OSHA-20

OCT 6 1980 S TION V - HEALTH HAZARD DAT							
THRESHOLD LIMIT VALUE							
EFFECTS OF OVEREXPOSURE							
		<u> </u>					
EMERGENCY AND FLUSH SKIN OF	FIRST EYE	AID PROCEDU S WITH WA'	TER. INGE	ESTION,	DO NOT INDUCE	VOMITING, SEE A PHYSICIAN	•
			()	5 , 2			
			SECTION	IVI - R	EACTIVITY DA	TA	
STABILITY	UNSTABLE		C	CONDITIONS TO AVOID			
	STAI	BLE	х	÷- •	•		
INCOMPATABILITY	(Mater	rials to avoid)	STRONG	OXIDIZ	ING AGENTS.		
HAZARDOUS DECO UPON COMBUSTI	MPOSI	TION PRODUC	CTS				
	.ON:	MAY OCCUP	CO, CO ₂	7	CONDITIONS TO	AVOID	
HAZARDOUS POLYMERIZATION		WILL NOT C	CCUR	х			
		<u></u>					
					OR LEAK PROC	EDURES	
STEPS TO BE TAKE	NINC	ASE MATERI	AL IS RELEA	ASED OR S	SPILLED		
CLEAN UP WITH	LOIL	A R SOR RENT	r MATERTA	ΛT., _			
WASTE DISPOSAL N	METHO	D	IMITALL	×10 •			
DISPOSE OF IN	AUT	HORIZED LA	NDFILL.				
	· · ·						
		· ·		ECIAL P	ROTECTION IN	FORMATION	
RESPIRATORY PROTECTION (Specify type)							
VENTILATION		LOCAL EXHAUST				SPECIAL	
	MEC	HANICAL (Ger	iera!)			OTHER	
PROTECTIVE GLOVES NEOPRENE SAFETY GLASSES OR GOGGLES.							
OTHER PROTECTIV	E EQU	IPMENT					
					CIAL PRECAUT	IONS	
PRECAUTIONS TO E	BE TAP	CEN IN HAND	LING AND S	TORING			
OTHER PRECAUTIO	NS						
]
· · · · · · · · · · · · · · · · · · ·					•	r 0011	

PAGE (2)

68010

R. E. Klotz, Technical Director R. E. Wolz